

REMARKS

Main claim 26 was amended to include the subject matter of canceled claim 30 and to better recite the structure of the second resilient member 40 with its eyelet 41. Thus, the second resilient member has side walls extending from opposite sides of the handle portion and meeting at the bottom edge. Also, the eyelet extends between these side walls lengthwise of the handle portion along the handle direction from the front edge of the sidewalls through the rear edge of the side walls.

By contrast, the only reference which discloses an eyelet is Reynolds in which Fig. 6 thereof discloses a hole (adjacent reference numeral 34') which does not extend lengthwise of the handle, but widthwise thereof. As explained at page 10, lines 23-25, this feature enables the reader to be mounted upright on a vertical pin or stud on a work surface so as to form a stand.

Wherefore, a favorable action is earnestly solicited.

Respectfully submitted,

KIRSCHSTEIN, OTTINGER, ISRAEL & SCHIFFMILLER, P.C.

Attorneys for Applicant(s)

489 Fifth Avenue

New York, New York 10017-6105

Tel: (212) 697-3750

Fax: (212) 949-1690

Alan Israel
Reg. No. 27,564

